

Service Bulletins

The following service bulletins are all active. Please check the applicability of each service bulletin as some may or may not apply to your aircraft.

SERVICE BULLETIN	TITLE	URGENCY	LINK
CH-11-08	Wing support brackets	Before further flight	Service bulletin PDF
CH/001/09-2009	Control stick hinge bolt	Before further flight	Service bulletin PDF
CH/002/09-2009	Electrical cable gauge	Before further flight	Service bulletin PDF
CH/003/12-2009	Elevator control arm and tie brace	Before further flight	Service bulletin PDF
C/ 000/06-2010	500Hr bolt replacement	Before further flight	Service bulletin PDF
CH/004/08-2011	Front fork fatigue cracks	Before further flight	Service bulletin PDF
CH/005/04-2018	BRS parachute assembly	Before further flight	Service bulletin PDF
SA/006/06-2018	Amendments to operating limitations	Before further flight	Safety alert PDF
CH/007/08-2018	Vortex generator installation	Next service interval	Service bulletin PDF Installation manual (adhesive type) Installation manual (glue type) Video install tutorial Cheetah XLS POH amendment pages Updated BushCat POH
CH/008/09-2018	BRS parachute assembly	Before further flight	Service bulletin PDF
CH/009/04-2019	Fuel tank integrity inspection	Before further flight	Service bulletin PDF
CH/010/05-2019	Fuel tank gasket inspection	Before further flight	Service bulletin PDF BCUG-068-001 PDF
SA/011/08-2019	Optional use of airspeed indicators with units/sub-scale in Knots	After change of instrument before further flight	Safety alert PDF
CH/012/06-2020	Engine mount adapter bolts	Before further flight	Service bulletin PDF
CH/014/10-2020	Pitot tube static ports	Before further flight	Service bulletin PDF
SB-912-074UL	From ROTAX: Exchange of floats (pair) on ROTAX® Engine Type 912, 914 and 2-stroke (Series)	Mandatory	Service bulletin PDF
CH/015/05-2021	Radius block washers (Nose-wheel kit builds)	Next service interval	Service bulletin PDF
CH/016/11-2021	Seat-belt unravelling	Before further flight	Safety Directive PDF
CH/017/07-2022	T-throttle inspection for older aircraft	Superseded by CH/018/10-2022	See CH/018/10-2022
CH/018/10-2022	T-throttle inspection for older aircraft	Before further flight	Service bulletin PDF
CH/019/03-2023	Trilam Inspection Schedule	Next service interval	Service bulletin PDF
SL/020/10-2023	Updated CG Envelope	Advisory letter	Service letter PDF
CH/021/06-2024	Various fatigue findings on high hour aircraft	Mandatory	Safety Directive PDF

